



Installation, Operation and Maintenance Instructions

Flowserve Corporation Flow Control Division 1350 N. Mountain Springs Parkway Springville, Utah 84663-3004 www.flowserve.com

Phone: 801 489 2234 Facsimile: 801 489 2228

Centura Analog Output Options Calibration and Operating Instructions

Electrical Specifications

Resistive feedback modules use a 1% linearity precision potentiometer operated by precision gears. The current feedback option combines the potentiometer with a 4-20 mA transmitter card.

ТҮРЕ ТХ	TYPE P2	TYPE P3	TYPE P4
4-20 mA Current Transmitter Voltage required: 6-30 Vdc Input resistance: 750 ohms max. @ 24 Vdc Temp. range: 32 to 158°F	0-1 K ohm resistive 1 Watt max. load Temp. range: 32 to 158°F	0-5K ohm resistive 1 Watt max. load Temp. range: 32 to 158°F	0-10 K ohm resistive 1 Watt max. load Temp. range: 32 to 158°F

NOTE: 1. Both resistive and current feedback signals are geared for quarter turn operation. Consult factory for other rotations. 2. The 'TX' option is a loop powered transmitter. For 'TT' options (transmitter with servo) see IOM for electronic servo position.

Caution: To Prevent ignition of hazardous atmospheres, keep unit tight

while circuits are alive. Disconnect supply circuit before opening.

Division 1 applications must be calibrated in a secured area.

Calibration

Resistive Feedback:

- 1. Remove cover and rotate actuator/valve to fail or start position.
- 2. Note desired resistance values at fail or start position.
- 3. Connect an ohmmeter to feedback terminals.
- 4. Using a 0.035 allen hex driver, loosen the set screw on the potentiometer gear. With a flat blade screwdriver, rotate the end of the potentiometer shaft to yield desired resistance.
- 5. Alternatively, the jam nut holding the potentiometer to the bracket may be loosened. Slide the potentiometer and gear away from the camshaft gear and rotate to desired resistance. Re-align and tighten.
- Rotate actuator/valve to end position. Check that resistance increases (or decreases) over stroke and that the potentiometer does not rotate past maximum (or minimum) resistance.
- 7. Replace cover.

4-20 mA Current Transmitter:

Figure 1 shows a diagram of the transmitter board and all necessary current loop components for calibration.

- 1. The controller board action DIP switch selects direction. For 4 mÅ in the full clockwise direction, select "D".
 - For 4 mA in the full counterclockwise direction, select "R". The factory setting is "D".

Note: Steps 2 through 4 are normally not necessary.

- 2. Rotate actuator/valve to mid position (45 degrees or 50%).
- 3. Using a 0.035 allen hex driver, loosen the set screw on the potentiometer gear. With a flat blade screwdriver, rotate the end of the potentiometer shaft to yield desired resistance.
- 4. Alternatively, the jam nut holding the potentiometer to the bracket may be loosened. Slide the potentiometer and gear from the camshaft gear and rotate to desired resistance. Re-align and tighten.
- 5. Rotate actuator/valve to fail or start position.
- 6. Adjust controller board zero trim pot. to yield 4 mA.
- 7. Rotate actuator/valve to end position.
- 8. Adjust controller board span trim pot. to yield 20 mA.
- 9. The zero and span adjustments are interactive. Repeat steps 5 through 8 until further zero adjustment does not affect span and vice versa.
- 10. Disconnect test equipment (if necessary) and replace cover.

Note: If transmitter adjustment gets difficult (i.e., trim pots do not have desired effect) start over by "centering" the trim pots. This is accomplished by turning in one direction 20 turns or until a clicking is heard. Turn in the opposite direction 10 turns. Repeat for other trim pot. Start calibration over at step 2.

Accord Controls FLOWSERVE Installation, Operation and Maintenance Instructions 1350 N. Mountain Springs Parkway **Flowserve Corporation** Phone: 801 489 2234 Springville, Utah 84663-3004 Flow Control Division Facsimile: 801 489 2228 www.flowserve.com USER-PROVIDED ACTION SWITCH SPAN TRIM TEST EQUIPMENT POT ZERO TRIM POT Ζ R D + м. BROWN RED LED DRANGE INDICATOR POWER DC mA METER POTENTIOMETER 4-20 mA TRANSMITTER BOARD

Figure 1 – 4-20 mA Transmitter Diagram

Troubleshooting

Problem	Probable Cause/Solution	
Output is not continuous throughout actuator/valve stroke (experience a band of max. output)	Potentiometer is out of adjustment (see "Resistive Feedback Calibration" or 4-20 mA Current Transmitter Calibration" steps 2-4).	
Transmitter does not out 4 or 20 mA at desired end of travel.	Zero or span trim potentiometer is out of adjustment (see 4-20 mA Current Transmitter Calibration).	
Transmitter module does not provide current signal or provide constant signal.	Circuit Board LED not lit: 1. Loose or shorted signal connection (no loop power). 2. Controller board not responding (replace board).	
	Circuit Board LED lit:1. Potentiometer disengaged.2. Defective potentiometer or controller board. Replace defective component.	
Output not linear or does not track valve position/rotation	Input signal not linear. Linkage or drive mechanism is introducing non-linearity. Zero span trim potentiometer is out of adjustment (see 4-20 mA Current Transmitter Calibration).	